

Sacramento County Superintendent of Schools
WILLIAMS SETTLEMENT LEGISLATION
RESULTS OF WILLIAMS SITE REVIEWS FOR ROBLA SCHOOL DISTRICT
2019-2020 FISCAL YEAR

This report summarizes the results of the 2019-2020 *Williams* Site Visits and documentation reviews at decile 1, 2, and 3 schools (2012 Base Academic Performance Index) conducted in August 2019.

School Name	Textbooks Review Date	Textbooks Results	Facilities Review Date	Facilities Inspection Rating
Bell Avenue Elementary School	8/27/2019	Sufficient	8/28/2019	Good
* Glenwood Elementary School	8/28/2019	Sufficient	8/28/2019	Good
Taylor Street Elementary School	8/27/2019	Sufficient	8/28/2019	Good

* *Unannounced visit(s)*

Sacramento County Office of Education
School Facility Conditions Evaluation
Based on the Office of Public School Construction
Facility Inspection Tool

District: Robla School District

School Site: Bell Avenue Elementary School

Inspection Date: 8/28/19

Number of Areas Evaluated: 15

Category Ranking

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Fair

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education
School Facility Conditions Evaluation
Based on the Office of Public School Construction
Facility Inspection Tool

District: Robla School District

School Site: Glenwood Elementary School

Inspection Date: 8/28/19

Number of Areas Evaluated: 14

Category Ranking

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education
School Facility Conditions Evaluation
Based on the Office of Public School Construction
Facility Inspection Tool

District: Robla School District

School Site: Taylor Street Elementary School

Inspection Date: 8/28/19

Number of Areas Evaluated: 16

Category Ranking

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Fair

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.