

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Robla School District

School Site: Bell Avenue Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 12/23/2020

Number of Areas Evaluated: 23

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Poor

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Poor

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Fair: The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Robla School District

School Site: Glenwood Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 12/24/2020

Number of Areas Evaluated: 27

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Robla School District

School Site: Taylor Street Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 1/4/2021

Number of Areas Evaluated: 36

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Fair

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.