

**Sacramento County Superintendent of Schools**  
**WILLIAMS SETTLEMENT LEGISLATION**  
**RESULTS OF WILLIAMS SITE REVIEWS FOR RIVER DELTA UNIFIED SCHOOL DISTRICT**  
**2019-2020 FISCAL YEAR**

This report summarizes the results of the 2019-2020 *Williams* Site Visits and documentation reviews at decile 1, 2, and 3 schools (2012 Base Academic Performance Index) conducted in August 2019.

School Name	Textbooks Review Date	Textbooks Results	Facilities Review Date	Facilities Inspection Rating
Clarksburg Middle School	8/20/2019	Sufficient	8/27/2019	Exemplary
Walnut Grove Elementary School	8/20/2019	Sufficient	8/27/2019	Exemplary

\* *Unannounced visit(s)*

**Sacramento County Office of Education**  
**School Facility Conditions Evaluation**  
Based on the Office of Public School Construction  
Facility Inspection Tool

District: River Delta Unified School District

School Site: Clarksburg Middle School

Inspection Date: 8/27/19

Number of Areas Evaluated: 17

**Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

**School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

**Sacramento County Office of Education**  
**School Facility Conditions Evaluation**  
Based on the Office of Public School Construction  
Facility Inspection Tool

District: River Delta Unified School District  
School Site: Walnut Grove Elementary School  
Inspection Date: 8/27/19  
Number of Areas Evaluated: 19

**Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good  
Interior surfaces: Good  
Cleanliness (Overall cleanliness, pest or vermin infestation): Good  
Electrical: Good  
Restrooms and Fountains: Good  
Safety (Fire safety and hazardous materials): Good  
Structural (Structural damage and roofs): Good  
External (Playground, school grounds, windows, doors, and fences): Good

**School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.