

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: River Delta Unified School District

School Site: Clarksburg Middle School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 12/8/2020

Number of Areas Evaluated: 3

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Poor

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Poor

Restrooms and Fountains: Poor

Safety (Fire safety and hazardous materials): Poor

Structural (Structural damage and roofs): Poor

External (Playground, school grounds, windows, doors, and fences): Poor

School Rating and Description

Poor: The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: River Delta Unified School District
School Site: Walnut Grove Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 12/10/2020
Number of Areas Evaluated: 3

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Fair
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Poor
Safety (Fire safety and hazardous materials): Poor
Structural (Structural damage and roofs): Poor
External (Playground, school grounds, windows, doors, and fences): Poor

School Rating and Description

Poor: The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.