

Sacramento County Superintendent of Schools
WILLIAMS SETTLEMENT LEGISLATION
RESULTS OF WILLIAMS SITE REVIEWS FOR NATOMAS UNIFIED SCHOOL DISTRICT
2019-2020 FISCAL YEAR

This report summarizes the results of the 2019-2020 *Williams* Site Visits and documentation reviews at decile 1, 2, and 3 schools (2012 Base Academic Performance Index) conducted in August 2019.

School Name	Textbooks Review Date	Textbooks Results	Facilities Review Date	Facilities Inspection Rating
American Lakes Elementary School	8/15/2019	Sufficient	8/15/2019	Exemplary
Bannon Creek Elementary School	8/15/2019	Sufficient	8/15/2019	Exemplary
* Jefferson Elementary School	8/19/2019	Sufficient	8/19/2019	Exemplary
* Natomas High School	8/30/2019	Sufficient	8/30/2019	Exemplary
Natomas Middle School	8/21/2019	Sufficient	8/21/2019	Exemplary
Two Rivers Elementary School	8/16/2019	Sufficient	8/16/2019	Exemplary

* *Unannounced visit(s)*

Sacramento County Office of Education
School Facility Conditions Evaluation
Based on the Office of Public School Construction
Facility Inspection Tool

District: Natomas Unified School District
School Site: American Lakes Elementary School
Inspection Date: 8/15/19
Number of Areas Evaluated: 20

Category Ranking

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education
School Facility Conditions Evaluation
Based on the Office of Public School Construction
Facility Inspection Tool

District: Natomas Unified School District
School Site: Bannon Creek Elementary School
Inspection Date: 8/15/19
Number of Areas Evaluated: 25

Category Ranking

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education
School Facility Conditions Evaluation
Based on the Office of Public School Construction
Facility Inspection Tool

District: Natomas Unified School District
School Site: Jefferson Elementary School
Inspection Date: 8/19/19
Number of Areas Evaluated: 21

Category Ranking

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education
School Facility Conditions Evaluation
Based on the Office of Public School Construction
Facility Inspection Tool

District: Natomas Unified School District

School Site: Natomas High School

Inspection Date: 8/30/19

Number of Areas Evaluated: 34

Category Ranking

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education
School Facility Conditions Evaluation
Based on the Office of Public School Construction
Facility Inspection Tool

District: Natomas Unified School District

School Site: Natomas Middle School

Inspection Date: 8/21/19

Number of Areas Evaluated: 24

Category Ranking

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education
School Facility Conditions Evaluation
Based on the Office of Public School Construction
Facility Inspection Tool

District: Natomas Unified School District
School Site: Two Rivers Elementary School
Inspection Date: 8/16/19
Number of Areas Evaluated: 16

Category Ranking

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

*Note: An extreme deficiency in any area automatically results in a “poor” ranking for that category.