

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: A. M. Winn Waldorf-Inspired K-8

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/10/2021

Number of Areas Evaluated: 35

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Abraham Lincoln Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/10/2021

Number of Areas Evaluated: 35

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Poor

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Poor

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Alice Birney Waldorf-Inspired K-8 School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/19/2021

Number of Areas Evaluated: 35

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District

School Site: Arthur A. Benjamin Health Professions High School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/11/2021

Number of Areas Evaluated: 38

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Poor

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Bret Harte Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/17/2021

Number of Areas Evaluated: 47

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Ethel I. Baker Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/17/2021

Number of Areas Evaluated: 42

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Ethel Phillips Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/17/2021

Number of Areas Evaluated: 47

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Father Keith B. Kenny Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/17/2021

Number of Areas Evaluated: 35

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Fern Bacon Middle School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/10/2021

Number of Areas Evaluated: 63

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Hiram W. Johnson High School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/18/2021

Number of Areas Evaluated: 122

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: John Cabrillo Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/18/2021

Number of Areas Evaluated: 37

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Poor

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: John D. Sloat Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/11/2021

Number of Areas Evaluated: 27

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: John H. Still K-8 Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/10/2021

Number of Areas Evaluated: 38

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: John H. Still K-8 Middle School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/10/2021

Number of Areas Evaluated: 56

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Poor

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Fair

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Kit Carson International Academy

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/11/2021

Number of Areas Evaluated: 59

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Leataata Floyd Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/11/2021

Number of Areas Evaluated: 41

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Luther Burbank High School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/9/2021
Number of Areas Evaluated: 140

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Poor
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Mark Twain Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/11/2021

Number of Areas Evaluated: 30

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Poor

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Martin Luther King Jr. K-8 School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/12/2021

Number of Areas Evaluated: 46

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Poor

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Nicholas Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/11/2021

Number of Areas Evaluated: 44

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District

School Site: Oak Ridge Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/17/2021

Number of Areas Evaluated: 44

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Pacific Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/16/2021

Number of Areas Evaluated: 43

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Fair

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Parkway Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/18/2021

Number of Areas Evaluated: 45

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Peter Burnett Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/16/2021

Number of Areas Evaluated: 45

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Rosa Parks K-8 School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/11/2021

Number of Areas Evaluated: 60

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Susan B. Anthony Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/22/2021

Number of Areas Evaluated: 39

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Fair

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Tahoe Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/11/2021

Number of Areas Evaluated: 32

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Sacramento City Unified School District
School Site: Woodbine Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 2/17/2021

Number of Areas Evaluated: 34

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.