

# **Sacramento County Office of Education 2021-22 Williams Site Review Summary**

District: Elverta Joint School District  
School Site: Elverta Elementary School

## **Instructional Materials Site Review**

Result: Sufficient

## **School Facility Inspection Review**

Inspection Date: 08/25/2021  
Number of Areas Evaluated: 12

### **Category Ranking\***

Systems (Gas leaks, mechanical, HVAC, sewer): Good  
Interior surfaces: Good  
Cleanliness (Overall cleanliness, pest or vermin infestation): Good  
Electrical: Good  
Restrooms and Fountains: Good  
Safety (Fire safety and hazardous materials): Good  
Structural (Structural damage and roofs): Good  
External (Playground, school grounds, windows, doors, and fences): Good

### **School Rating and Description**

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

\* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.