

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District
School Site: D.W. Babcock Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 08/30/2021

Number of Areas Evaluated: 19

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Poor

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District
School Site: Del Paso Heights Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 09/02/2021

Number of Areas Evaluated: 19

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Poor

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Dry Creek Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 08/27/2021

Number of Areas Evaluated: 19

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District
School Site: Elwood J. Keema High School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 09/08/2021

Number of Areas Evaluated: 9

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Fairbanks Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 09/03/2021

Number of Areas Evaluated: 18

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Fair

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Foothill High School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 08/30/2021

Number of Areas Evaluated: 47

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Fair

Restrooms and Fountains: Fair

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District
School Site: Foothill Oaks Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 08/24/2021

Number of Areas Evaluated: 25

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Foothill Ranch Middle School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 09/10/2021

Number of Areas Evaluated: 29

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District
School Site: Frederick C. Joyce Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 09/02/2021

Number of Areas Evaluated: 23

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Fair

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District
School Site: Garden Valley Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 09/03/2021
Number of Areas Evaluated: 15

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Grant Union High School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 09/08/2021

Number of Areas Evaluated: 60

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District
School Site: Hagginwood Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 08/24/2021

Number of Areas Evaluated: 26

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Highlands High School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 09/10/2021

Number of Areas Evaluated: 28

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Fair

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Kohler Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 09/10/2021

Number of Areas Evaluated: 19

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Fair

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District
School Site: Martin Luther King, Jr. Technology Academy

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 08/31/2021
Number of Areas Evaluated: 25

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Fair
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Fair
Restrooms and Fountains: Poor
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District
School Site: Michael J. Castori Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 09/02/2021

Number of Areas Evaluated: 22

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Poor

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District
School Site: Northwood Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 08/24/2021

Number of Areas Evaluated: 24

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Fair

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Norwood Junior High School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 09/14/2021

Number of Areas Evaluated: 21

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Orchard Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 08/25/2021

Number of Areas Evaluated: 25

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District
School Site: Pioneer Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 08/23/2021

Number of Areas Evaluated: 27

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District
School Site: Rio Linda Preparatory Academy

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 09/09/2021

Number of Areas Evaluated: 18

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Fair

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Rio Tierra Junior High School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 09/02/2021

Number of Areas Evaluated: 16

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District
School Site: Sierra View Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 08/26/2021

Number of Areas Evaluated: 12

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Village School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 08/26/2021

Number of Areas Evaluated: 17

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Poor

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Warren A. Allison Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 09/27/2021

Number of Areas Evaluated: 19

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Fair

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Westside Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 08/27/2021

Number of Areas Evaluated: 15

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Fair

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Woodlake Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 08/30/2021

Number of Areas Evaluated: 18

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Fair

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Good: The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2021-22 Williams Site Review Summary

District: Twin Rivers Unified School District

School Site: Woodridge Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 08/31/2021

Number of Areas Evaluated: 25

Category Ranking*

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.