

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Natomas Unified School District
School Site: American Lakes Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 10/13/2020

Number of Areas Evaluated: 10

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Natomas Unified School District
School Site: Bannon Creek Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 11/12/2020
Number of Areas Evaluated: 9

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Natomas Unified School District
School Site: Jefferson Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 11/17/2020

Number of Areas Evaluated: 11

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Natomas Unified School District

School Site: Natomas High School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 12/8/2020

Number of Areas Evaluated: 15

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Natomas Unified School District

School Site: Natomas Middle School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 11/19/2020

Number of Areas Evaluated: 16

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good

Interior surfaces: Good

Cleanliness (Overall cleanliness, pest or vermin infestation): Good

Electrical: Good

Restrooms and Fountains: Good

Safety (Fire safety and hazardous materials): Good

Structural (Structural damage and roofs): Good

External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.

Sacramento County Office of Education 2020-21 Williams Site Review Summary*

District: Natomas Unified School District
School Site: Two Rivers Elementary School

Instructional Materials Site Review

Result: Sufficient

School Facility Inspection Review

Inspection Date: 11/19/2020
Number of Areas Evaluated: 10

Category Ranking**

Systems (Gas leaks, mechanical, HVAC, sewer): Good
Interior surfaces: Good
Cleanliness (Overall cleanliness, pest or vermin infestation): Good
Electrical: Good
Restrooms and Fountains: Good
Safety (Fire safety and hazardous materials): Good
Structural (Structural damage and roofs): Good
External (Playground, school grounds, windows, doors, and fences): Good

School Rating and Description

Exemplary: The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.

* The district conducted its own school facility inspection review due to COVID-19. This summary reflects the information the district reported to SCOE.

** Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category.